




**WELLINGTON  
ENVIRONMENTAL**  
*Your World: Cleaner, Better, Safer*

## CASE STUDY SPOTLIGHT: BATS IN THE BELFRY

General contractors are often called upon to solve unique problems for clients. In this case, a general contractor was needed to fabricate and install protective grills in all of the church steeple's openings to prevent bats and birds from calling the steeple home. However, prior to performing the work – someone was needed to clean out all the bats and the debris that they along with their bird friends created in this tall belltower. We also temporarily sealed up the openings to that the general contractor did not have more winged visitors. Projects like this are our specialty.

### BEFORE PHOTOS





**WELLINGTON  
ENVIRONMENTAL**  
*Your World: Cleaner, Better, Safer*

## CASE STUDY SPOTLIGHT: BATS IN THE BELFRY

### AFTER PHOTOS

